

IECEX Quality Assessment Report: DE/TUR/QAR10.0001/02 details

QAR :																																														
QAR Reference Number*: (automatic numbering)	DE/TUR/QAR10.0001/02																																													
Related QARs:	DE/TUR/QAR10.0001/01 DE/TUR/QAR10.0001/00																																													
Status*:	Issued																																													
QAR Free Reference Number*:	124875693																																													
Audit Date*: (yyyy-mm-dd)	2016-02-11																																													
Date of Issue*: (yyyy-mm-dd)	2016-04-04																																													
Details of change*:	Reassessment																																													
Valid until*: (yyyy-mm-dd)	2019-03-01																																													
Site(s) audited*:	Watlow Hannibal 6 Industrial Loop Drive Hannibal, MO 63401																																													
Issuing ExCB*:	TUR - TUV Rheinland Industrie Service GmbH																																													
Manufacturer*:	Watlow Hannibal 6 Industrial Loop Drive Hannibal, MO 63401																																													
Country of Manufacture*:	United States of America																																													
Product information*:	Flange Immersion Heaters																																													
Protection concept*:	"d" flameproof enclosure "e" increased safety																																													
Related IECEX Certificates: (automatic linking)																																														
Related Certificates: (manual insertion)																																														
Related IECEX Certificates for previous versions:																																														
	<table border="0"> <thead> <tr> <th>ExCB name</th> <th>CoC and Status</th> <th>Totals</th> </tr> </thead> <tbody> <tr> <td><input type="checkbox"/> CSA International</td> <td></td> <td>8</td> </tr> <tr> <td></td> <td>IECEX CSA 15.0025X issue: 0 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CSA 13.0007U issue: 1 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CSA 13.0007U issue: 0 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CSA 09.0010X issue: 4 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CSA 09.0010X issue: 3 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CSA 09.0010X issue: 2 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CSA 09.0010X issue: 1 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX CSA 09.0010 issue: 0 [Current]</td> <td></td> </tr> <tr> <td><input type="checkbox"/> SIRA Certification Service</td> <td></td> <td>3</td> </tr> <tr> <td></td> <td>IECEX SIR 12.0056X issue: 2 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX SIR 12.0056X issue: 1 [Current]</td> <td></td> </tr> <tr> <td></td> <td>IECEX SIR 12.0056X issue: 0 [Current]</td> <td></td> </tr> <tr> <td></td> <td></td> <td>11</td> </tr> </tbody> </table>	ExCB name	CoC and Status	Totals	<input type="checkbox"/> CSA International		8		IECEX CSA 15.0025X issue: 0 [Current]			IECEX CSA 13.0007U issue: 1 [Current]			IECEX CSA 13.0007U issue: 0 [Current]			IECEX CSA 09.0010X issue: 4 [Current]			IECEX CSA 09.0010X issue: 3 [Current]			IECEX CSA 09.0010X issue: 2 [Current]			IECEX CSA 09.0010X issue: 1 [Current]			IECEX CSA 09.0010 issue: 0 [Current]		<input type="checkbox"/> SIRA Certification Service		3		IECEX SIR 12.0056X issue: 2 [Current]			IECEX SIR 12.0056X issue: 1 [Current]			IECEX SIR 12.0056X issue: 0 [Current]				11
ExCB name	CoC and Status	Totals																																												
<input type="checkbox"/> CSA International		8																																												
	IECEX CSA 15.0025X issue: 0 [Current]																																													
	IECEX CSA 13.0007U issue: 1 [Current]																																													
	IECEX CSA 13.0007U issue: 0 [Current]																																													
	IECEX CSA 09.0010X issue: 4 [Current]																																													
	IECEX CSA 09.0010X issue: 3 [Current]																																													
	IECEX CSA 09.0010X issue: 2 [Current]																																													
	IECEX CSA 09.0010X issue: 1 [Current]																																													
	IECEX CSA 09.0010 issue: 0 [Current]																																													
<input type="checkbox"/> SIRA Certification Service		3																																												
	IECEX SIR 12.0056X issue: 2 [Current]																																													
	IECEX SIR 12.0056X issue: 1 [Current]																																													
	IECEX SIR 12.0056X issue: 0 [Current]																																													
		11																																												

Comment:

Attachment:

Last modified: 08.04.2016 08:21:07

Copyright © IEC-IECEX 2016 , Geneva, Switzerland. All rights reserved.